

IN THE SPECIFICATION:

Please replace the paragraph starting at page 16, line 24, with the following amended paragraph:

As can best be seen in FIGS 15 and 17, the actuator (16') includes a motor (70') with a screw (72'). The actuator (16') is located within the interior of the middle section (14B') so as to be surrounded by the walls (308, 310, 312), with the screw (72') extending beyond the upper end ~~[(314)] (312)~~ and between the flanges (26') of the knee member (12'). The screw (72') engages a follower (74') forming part of the pivot assembly (80') that is connected to the knee member (12') at a location spaced from the pivot assembly (30').